Demarcation Buoys,

Outreach, Monitoring & Enforcement Activities Related to the Marine Life Protection Act

SEABIRD PROTECTION NETWORK

Sage Tezak Coordinator, Seabird Protection Network August 11, 2011

Overview

- Seabird Protection Network
- Operation Buoys for Special Closures
- Other Activities Related to the Marine Life Protection Act




How our Goals Align

- Seabird Protection Network
 - Improve survival of California's seabird species by reducing disturbance at their breeding and roosting colonies
- Marine Life Protection Act's Special Closures
 - Protection for breeding and roosting seabirds; rookeries and haul-out areas for marine mammals
- A Natural Fit
 - Tasked with installing and maintaining year-round & seasonal buoys used to demarcate Special Closures
 - Additional efforts to help inform boaters about MPAs

Buoys:Long-term Installation Plan

- Devil's Slide Rock (4)
- Point Resistance (2)
- Ouble Point (3)
- Southeast Farallon Is. (8)
- North Farallon Is. (3)
- Pt. Reyes (4)
- 24 demarcation buoys within the Gulf of Farallones and Monterey Bay National Marine Sanctuaries



Installation Plan: Phased Approach

- Buoy installation in 3-4 phases
 - Phase I: Devil's Slide Rock (4)
 - Completed: April 30, 2011
 - Phase II: Pt. Resistance (2), Double Point (3)
 - Proposed: October 2011
 - Phase III: S.E. Farallon Is. (8), N. Farallon Is. (3)
 - Phase IV: Point Reyes (4) if sign is not effective


Buoys: Physical Characteristics

- Rotationally molded UV-stabilized virgin polyethylene
- Filling: Closed-cell polyurethane foam
- Wall thickness: 1/4 inch
- Ballast: 40 lbs.
- Height: 57 1/8 inch
 - Above water: 45 ⁵/₈ inch
- Width: 25 2/3 inch
- Mass: 73 lbs.
- Life expectancy: Up to 12 years
- Color: white
- Reserve buoyancy: 132 lbs.




Buoy System

- Buoys (700 mm. dia. Sealite)
- Anchors (300 lb. DorMor)
- Rode:
 - Oceanographic rope
 - ¾" galvanized steel chain
 - ½" galvanized steel chain
- Hardware: stainless steel thimbles, shackles, swivels, double barrel sleeves




Phase I: Lessons Learned

- 3 buoys installed:
 - **DSR #1:** (360 ft. from shore) not in projected location
 - DSR #2: Sub-par drop within 2 ft. – 29.5–52.4ft
 - DSR #3: Spot on
 - DSR #4: 308ft. from shore; <~26ft water depth



Phase I: Lessons Learned



Challenges

- Limited facilities
- Surf-zone
- Depth (<60 ft.)

Equipment

- Buoys (700 mm. dia.)
 - Larger size
 - Mold-in graphics
- Rode:
 - Oceanographic rope (MBARI)
 - Rubber cord (CDIP)

Vessel Activity: Special Closures

Number of boats recorded in special closure areas			
	2008	2009	2010
Devil's Slide Rock Special Closure	14	16	2
Point Reyes Headlands Special Closure	3	1	1
Point Resistance Rock Special Closure	0	0	2
Double Point/Stormy Stack Special Closure	2	1	5

Reported in 2011


- 3 incidents at Devil's Slide Rock (2 involved same vessel)
- 2 incidents at Stormy Stack

One disturbance can destroy an entire colony!

Data collected by U.S. Fish & Wildlife Service, Monitoring component of the Seabird Protection Network

Looking into the Future

- Phase II scheduled to begin in October
- Next week
 - Technical Advisory Committee Meeting
 - Provide guidance on the best way forward




Activities to Inform Boaters about Marine Protected Areas

- Comprehensive Boater Education Program
- Mailing to over 350 boating facilities, interest groups
- Way-side
 interpretive
 signage



Activities to Inform Boaters about Marine Protected Areas

- Boater & Kayaking Guide
- Assisting with California Department of Fish & Game with interpretive enforcement
- Aerial vessel use surveys



Thank you!

Questions?